

ENGINEERING CHANGE NOTICE **DART AEROSPACE LTD**

Date: 09.01.08	Job No.: P00569	ADR Yes/No: Yes	ADR Date: 08.12.01	ECN #: 09- 501
Product No.: D407-663, D407-627	Created By: HS	Approved By: <i>[Signature]</i>		
Product Name: Heli-Utility Basket, Heli-Utility Pod	Checked By: <i>[Signature]</i>	General Manager Approval: <i>N/A</i>		

Distribution	Reqd	Resp	Initial / Date
Production Manager	Y	LL	<i>LL 09.01.15</i>
Production Engineering Coord	Y	EC	<i>EC 09.01.15</i>
Production Document Control	Y	JLB	<i>JLB 09.01.15</i>
Customer Technical Support	Y	DS	<i>DS 09.01.15</i>

Distribution	Reqd	Resp	Initial / Date
DQA / QA Coord	Y	SS	<i>SS 09.01.15</i>
QC Coordinator	N		
Marketing	Y	SW	<i>SW 09.01.15</i>
Customer Order Processing	N		

Reason for Change:
The manual release cable connection could become hung up on the center D2796 support due to mis-alignment. See NCR 08-076

Documents Affected:
DSI 9428 Rev. A
D3863 Rev. A

PARTS MUST COMPLY ☒ **PREVIOUS PARTS SATISFACTORY** ☐

#	Quality Assurance Actions	Reqd	Resp	Notes	Complete
1	Notify Previous Customers	Y	SW	Helicopter Transport	<i>SW 10.05.19</i>
2	Notify Eurocopter France	N			
3					

#	Engineering Actions	Reqd	Resp	Notes	Complete
4	Required Documents/Drawings Under Review	N			
5	Update Product Compatability Matrix	N			
6	Create Eurocopter Form (FEE)	N			
7	Notify TC / FAA of Change	N			

#	Document Control Actions	Reqd	Resp	Notes	Complete
8	Move Electronic Files	Y	KJ		<i>09.01.15</i>
9	Update Blue/Pink/DSI Folder and Electronic Files	Y	KJ		<i>09.01.14</i>
10	Update Controlled PDF Files	Y	KJ		<i>09.01.14</i>
11	Update Master Document List (MDL)	N			
12	Update Document Record (DR)	Y	KJ	<i>627 Rev L, 663 Rev D</i>	<i>09.01.15</i>
13	Update Product Development Summary	N			
14	Update QSI 021 and/or STC Approval List	N			
15	Update Parts / STC Database	Y	KJ		<i>09.01.14</i>
16	Update / Verify ARC Database	Y	KJ	<i>APPROVAL # 125 (627, 663-DSI)</i>	<i>09.01.14</i>
17	Create / Update Change Record Form	Y	KJ		<i>09.01.15</i>
18	Create / Update PPP's	Y	KJ		<i>09.01.15</i>
19	Update Document Control Database / Laminated Dwgs	N			
20	Update Grey Project Binder	Y	KJ	<i>Add ADR</i>	<i>09.01.15</i>
21	Update D-Part/M-Drawing/DSI/DEO Master Binders	Y	KJ		<i>09.01.15</i>
22					
23					

Description / Action:

- DSI 9428 completes the corrective action for NCR 08-076.
- After reviewing the information and pictures that the customer provided it was decided to use a plastic sleeve around the manual release cable connection to prevent it from hanging up on the D3796 support (D3863-1). DSI 9428 was created to show customers how to install the D3863-1 sleeve.
- Update estimates to indicate D3863-1 as part of D407-627-013 and D407-663-011
- D407-627-013 now at CHG 005
- D407-663-011 now at CHG 003
- Add (1x) D3863-1 as well as a copy of DSI 9428 to all D407-627-013 and D407-663-011 kits in stock and change product labels.
- *DSI 9428-011 NOW @ CHG 001*

APPROVAL # 125 FOR DSI 9428-011 (STC'S FROM 627 & 663)

ECN Verified & Complete: *[Signature]*

Date: *10/5/20*